Reference	Documentation Type	Preferred Protocol	Secondary Protocol	CUI/FOUO Protocol	NDA Protocol
Agile	Engineering Change Request	Agile	None - Must use Agile	Agile	None - Must use Agile
PR001294	AsBuilt	OSQRE [1]	FileZilla Upload	FileZilla	Utilize OSQRE1 and log into entity set up specifically for the product covered by the NDA.
QAPP 5	CERTIFICATE OF COMPLIANCE ("C of C")	OSQRE [1]		NA	Utilize OSQRE1 and log into entity set up specifically for the product covered by the NDA.
QAPPs 12A,B,C	FIRST ARTICLE INSPECTION ("FAI")	OSQRE [1]	Send hard copy with shipment		
QAPP 22	SUPPLIER FAILURE REPORTING, ANALYSIS AND CORRECTIVE ACTION SYSTEM ("FRACAS") REQUIRED	Send to applicable program Quality Engineer	Send to your Supply Chain Representative and copy the Quality Engineer.		Send to your Supply Chain Representative and copy the Quality Engineer.
QAPP 35	TEST & INSPECTION DATA	OSQRE [1]	Send hard copy with shipment		
QAPP 35A	TEST & INSPECTION DATA	OSQRE [1]	Test results can be provided electronically by submitting via email to viasattestdata@viasat.com. The email subject line and data file shall be in the following format (Viasat PN_YYMMDD_SN xxx thru SN xxx), and the email shall include the following information: (a) Part number and revision (b) Viasat PO number. (c) Supplier's acceptance test procedure number (if applicable) and revision date. (d) Date of test or inspection completion. (e) Evidence of test or inspection acceptance by Supplier's Quality Assurance representative.	OSQRE is required if supplier and program have been onboarded. If not, Lancer SFTP, verify with supply change representative and/or program manager	
QAPP 35B	AS-BUILT TRACEABILITY RECORD	OSQRE [1]	Utilize PR001294 procedure referencing the Filezilla process for submission.		
QAPP 39	SUPPLIER DESIGN PRODUCT AND PART, MATERIAL AND PROCESS ("PMP") CHANGE CONTROL	OSQRE [1]	Send the form PR002403 to your Supply Chain Representative and copy any applicable Program's Product Quality Engineering Representative.		
QAPP 40	VIASAT DESIGN PRODUCT AND PMP CHANGE CONTROL	OSQRE [1]			
QAPP 50 - 50D	PWB FAB DATA	OSQRE [1]	Send to your Supply Chain Representative.		
QAPP 55	REPAIR/SERVICE REPORTING	OSQRE [1]	Upon shipment, Supplier shall email the test data, results of such tests and service, and repair report to viasatrmareports@viasat.com, and the email subject line and data file shall be in the following format (Viasat PN_YYMMDD_SN xxx_NMR).		
QAPP 62	ENVIRONMENTAL PRODUCT REQUIREMENTS	OSQRE [1]	Email the required certifications upon shipment to viasattestdata@viasat.com and Compliance-ProductEnvironmental@viasat.com, and the email subject line and data file shall be in the following format (Viasat PN_YYMMDD_SN xxx thru SN xxx). Alternatively, a hard copy can be provided with the material.	NA	Utilize OSQRE1 and log into entity set up specifically for the product covered by the NDA.
QAPP 63 A	DECLARTION OF CONFORMITY FOR LOW VOLTAGE DIRECTIVE (LVD) & EMC DIRECTIVES CURRENTLY IN FORCE	OSQRE [1]		NA	
QAPP 63 B	CE OR CB SAFETY REPORT FOR EUROPEAN AND UK COMPLIANCE	OSQRE [1]			
QAPP 63 C	EMC TEST REPORT	OSQRE [1]			
QAPP 63 D	NRTL CERTIFCATE OF COMPLIANCE FOR NORTH AMERICA	OSQRE [1]			
QAPP 64	FCC ID AND ISED NUMBER FOR INTENTIONAL RADIATOR EQUIPMENT	OSQRE [1]			
PR002403	Process Flow Change	OSQRE [1]		NA	
PR002403	Equipment Transfer / Move to Different Location	OSQRE [1]			
PR002403	New/Upgraded Equipment	OSQRE [1]			
PR002403	Tooling not in use >1 yr	OSQRE [1]	Send the form PR002403 to your Supply Chain Representative and copy any applicable Program's Quality Engineering Representative.		
PR002403	New Sub-Tier Supplier	OSQRE [1]			
PR002403	Test Procedure/Equipment Change	OSQRE [1]			
PR002403	Other Process Change	OSQRE [1]			
		OSQRE [1]		Agile	None - Must use Agile

1 OSQRE (Operations Supplier Quality Record Exchange) is a portal for loading various documents prior to shipment and before acceptance (https://osqre.pte.viasat.us/ see Supplier Information Webpage for more information).